

☐ Toggle menu  
Blue Gold Program Wiki

## Navigation

- [Main page](#)
- [Recent changes](#)
- [Random page](#)
- [Help about MediaWiki](#)

## Tools

- [What links here](#)
- [Related changes](#)
- [Special pages](#)
- [Permanent link](#)
- [Page information](#)

## Personal tools

- [Log in](#)

## personal-extra

☐ Toggle search

Search

Random page

## Views

- [View](#)
- [View source](#)
- [History](#)
- [PDF Export](#)

## Actions

# File:Photo 3.1.jpg

From Blue Gold Program Wiki

The printable version is no longer supported and may have rendering errors. Please update your browser bookmarks and please use the default browser print function instead.

- [File](#)
- [File history](#)
- [File usage](#)



Size of this preview: [800 × 440 pixels](#). Other resolutions: [320 × 176 pixels](#) | [1,574 × 865 pixels](#).


[Original file](#) (1,574 × 865 pixels, file size: 258 KB, MIME type: image/jpeg)

A regulator draining excess water from Polder 31-part into the Kazibacha River

the principal function of a regulator or drainage sluice is to allow the drainage of water from the polder into a peripheral river when there is a differential head across the regulator (ie when the polder or country-side water level exceeds the level in the tidal river). The regulator is provided with a lift gate on the country-side (to allow freshwater to be held in the khal for irrigation during the dry season) and a flap gate on the river-side (to prevent water entry from the river channel into the polder during high tide conditions). A frame is provided on the river-side so that the flap gate can be lifted when there is freshwater in the river (during the monsoon flood season), thus allowing freshwater to be stored in the khal within the polder and used for irrigation during the dry season. The size of the culvert is determined from the drainage area served by the structure.

## File history

Click on a date/time to view the file as it appeared at that time.

Date/Time	Thumbnail	Dimensions	User	Comment
current <a href="#">04:20, 23 May 2021</a>		1,574 × 865 (258 KB)	<a href="#">Bigblue</a> ( <a href="#">talk</a>   <a href="#">contribs</a> )	

You cannot overwrite this file.

# File usage

The following 2 pages use this file:

- [03 Social, Physical and Environmental Context](#)
- [Summary of Section C: Water Infrastructure](#)

Retrieved from "[https://www.bluegoldwiki.com/index.php?title=File:Photo\\_3.1.jpg&oldid=5501](https://www.bluegoldwiki.com/index.php?title=File:Photo_3.1.jpg&oldid=5501)"

## Namespaces

- [File](#)
- [Discussion](#)

## Variants

This page was last edited on 23 May 2021, at 04:20.

# Blue Gold Program Wiki

The wiki version of the Lessons Learnt Report of the Blue Gold program, documents the experiences of a technical assistance (TA) team working in a development project implemented by the Bangladesh Water Development Board (BWDB) and the Department of Agricultural Extension (DAE) over an eight+ year period from March 2013 to December 2021. The wiki lessons learnt report (LLR) is intended to complement the BWDB and DAE project completion reports (PCRs), with the aim of recording lessons learnt for use in the design and implementation of future interventions in the coastal zone.

- [Privacy policy](#)
- [About Blue Gold Program Wiki](#)
- [Disclaimers](#)

Developed and maintained by Big Blue Communications for Blue Gold Program



[Blue Gold Program Wiki](#)